Rt pane – no visible leak
(yet).

rotted wood – moldy
left pane –
leak must have been present for many years.

leak caused
rotting wood / mold.

leak visible
when small amt of
water is squirted on window

faulty seal
between glass and aluminum.

faulty seal